




Installation

3-phase motor with fitted cable

4-core cable (Option: GV-therm 6 cores)

3-phase power supply: 3 x 400 Volt - 50 Hz or 3 x 230 Volt - 50 Hz



Other voltages and frequencies are available upon request.