




Installation

3-phase motor fitted with cable

7-core cable (Option: GV-therm 9 cores)

3-phase power supply: star connection (high voltage), delta connection (low voltage)



Other voltages and frequencies are available upon request.